

NARlabs 國家實驗研究院

國家地震工程研究中心

National Center for Research on Earthquake Engineering

Reconnaissance Report on Seismic Damage Caused by Guanshan Earthquake and Chihshang Earthquake, Taiwan, 2022 (third edition, v3.0)

Chung-Che Chou, Chiun-Lin Wu, Juin-Fu Chai, George C. Yao

**NCREE, Taiwan
September 23, 2022**

承諾 · 熱情 · 創新

Copyright © 2022 NCREE. All rights reserved.

www.narlabs.org.tw
www.ncree.narl.org.tw

Members of the Emergency Response Team

Chairperson: Chung-Che Chou

Emergency Response Operation Manager (Deputy Chairperson): Chiun-Lin Wu

Deputy Emergency Response Operation Manager: Juin-Fu Chai

Executive Secretary: Chi-Hao Lin

Disaster Estimation

Gee-Yu Liu 、 Yu-Wen Chang , Jyun-Yan Huang , Shih-Liang Chen, Lee-Hui Huang

Disaster Information Collection

Chun-Chung Chen , Hsiao-Hui Hung , Bo-Han Lee, Chih-Shian Chen

Damage Survey

Yuan-Tao Weng, Hsuan-Chih Yang

Emergency Response Support

Ho-Hsiung Yang, Wei-Choung Cheng, Mu-Hsuan Li, Hsien-chung Lin, Ruey-Chu Kao, Su-Yueh Lu, Chun-Yuan Ku, Chia-Chuan Hsu, Chung-Han Yu, Ching-Hsien Huang, Chiao-Chu Hsu, Che-Yu Chang, Shang-Yi Hsu, Jiun-Shiang Wang, Yu-Ying Lin, Kuan-Yu Chen, Chiu-Ping Fan, Chih-Wei Chang, You-Xuan Lin

Decision Making

Chin-Hsun Yeh, Fang-Yao Yeh, Jui-Liang Lin, Shu-Hsien Chao, Che-Min Lin

Members of Reconnaissance Team

Building and Bridge Damage Survey

Chung-Che Chou, Chung-Chan Hung, Gilberto Mosqueda, Zheng-Kuan Lee, Chi-Rung Jiang, Sheng-Jhih Jhuang, Kai-Ning Chi, Sheng-Yuan Siao, Jian-Ming Chen

Geological Damage Survey

Chih-Chieh Lu, Yuan-Chang Deng, Wei-Kuang Chang

Nonstructural Components and Systems Damage Survey

George C. Yao, Fan-Ru Lin, Wei-Hung Hsu, Bai-Yi Huang, Wei-Chung Chen, Yu-Chiau Huang, Jian-Xiang Wang, Tzu-Chieh Chien, Kun-Ru Liu, Min-Chi Ko, Chen-Pei Hsu, Tzu-Ying Wu

External Support

Taiwan professional geotechnical engineers association

CECI Engineering Consultants, Inc.

SINOTECH Engineering Consultants, Ltd.

Introduction

- ✦ At 9:41 p.m. on Sep. 17 (UTC+8) and 2:44 p.m. on Sep. 18 (UTC+8) in 2022, two M_L 6.4 and 6.8 earthquakes hit Guanshan and Chihshang in Taitung (respectively named as Guanshan earthquake and Chihshang earthquake). According to the Central Weather Bureau (CWB), the M_L 6.8 quake is the mainshock and the M_L 6.4 quake is the foreshock. The epicenters of the two quakes are both near the Chihshang fault. The ground shaking reaches CWB Seismic Intensity Level 6 Upper (6+) and the peak ground acceleration 607 gal, leading to disasters including building and bridge collapse in Hualien and Taitung. Within 1 hour after the mainshock, NCREE convened the seismic disaster emergency response meeting. Damage surveys were quickly planned and scheduled based on the early loss estimation results reported by the disaster estimation team and the latest disaster information reported by disaster information collection team. On the next day, Sep. 19, Director General, Chung-Che Chou, led members of Building Engineering Division, Bridge Engineering Division, Earth Sciences and Geotechnical Engineering Division, Nonstructural Components and Systems Division to conduct on-site damage survey in Hualien and Taitung, inspecting damage sites and collecting information about the cause of disasters.

- ✦ After the earthquakes, disaster information collection is gradually completed. Information of the earthquakes and the report of disasters is published on the NCREE official website.

2022
09/17

- Information of Guanshan and Chihshang earthquakes in Taitung

- Report in Chinese Ed. 1 (v1.2): uploaded on Sep. 18, 2022. <https://reurl.cc/aGDYX9>
- Report in Chinese Ed. 2 (v2.3): uploaded on Sep. 19, 2022. <https://reurl.cc/NRodM6>

Outline of Disaster Investigation Report

- ◆ Ground Motion Characteristics
- ◆ Damage of Buildings
- ◆ Damage of Bridges
- ◆ Geotechnical Damage
- ◆ Damage of Nonstructural Components and Nonbuilding Structures
- ◆ Information for Earthquake Early Warning, Structural Monitoring and Control

Outline of Disaster Investigation Report

◆ Ground Motion Characteristics

◆ Damage of Buildings

◆ Damage of Bridges

◆ Geotechnical Damage

◆ Damage of Nonstructural Components and Nonbuilding Structures

◆ Information for Earthquake Early Warning, Structural Monitoring and Control

CWB Earthquake Report

■ 【Earthquake No.: 111086】


Origin time (Taiwan Standard Time: GMT+08:00):
9/17/2022 21:41:19.1

Location: 23.08N 121.16E, i.e. 35.8 km N of
Taitung County

Depth : 7.3 km

Magnitude(M_L): 6.4

Guanshan Eqk.



CWB EARTHQUAKE REPORT

Earthquake No.: 111086
Origin time (Taiwan Standard Time: GMT+8):
9/17/2022 21:41:19.1
Epicenter: 23.08°N, 121.16°E,
i.e. 35.8 km N of Taitung County Hall
Focal depth: 7.3 km
Magnitude (ML): 6.4

Local Largest Intensity:

Taitung County	6+	Penghu County	2
Hualien County	5+	Taoyuan City	2
Kaohsiung City	5-	Hsinchu City	2
Nantou County	4	Taipei City	2
Tainan City	4	Keelung City	1
Chiayi County	4		
Yunlin County	4		
Pingtung County	4		
Chiayi City	4		
Changhua County	3		
Taichung City	3		
Miaoli County	3		
Yilan County	3		
Hsinchu County	3		
New Taipei City	3		

■ 【Earthquake No.: 111111】


Origin time (Taiwan Standard Time: GMT+08:00):
9/18/2022 14:44:15.2

Location: 23.14N 121.20E, i.e. 42.7 km N of
Taitung County

Depth : 7.0 km

Magnitude(M_L): 6.8

Chihshang Eqk.



CWB EARTHQUAKE REPORT

Earthquake No.: 111111
Origin time (Taiwan Standard Time: GMT+8):
9/18/2022 14:44:15.2
Epicenter: 23.14°N, 121.20°E,
i.e. 42.7 km N of Taitung County Hall
Focal depth: 7.0 km
Magnitude (ML): 6.8


Local Largest Intensity:

Taitung County	6+	Taoyuan City	3
Hualien County	6-	Penghu County	3
Nantou County	5-	Hsinchu City	3
Chiayi County	4	Taipei City	3
Kaohsiung City	4	Keelung City	2
Tainan City	4	Lienchiang County	1
Yunlin County	4		
Pingtung County	4		
Chiayi City	4		
Changhua County	4		
Taichung City	4		
Miaoli County	4		
Yilan County	4		
Hsinchu County	4		
New Taipei City	4		


According to the press conference of the CWB at 16:30 pm on September 18, the M_L 6.8 earthquake on September 18 was the main shock, and the M_L 6.4 earthquake on September 17 was the foreshock.

The Ground Motion Map from CWB

Guanshan Eqp. 0917M_L6.4




Chihshang Eqp. 0918M_L6.8



Focal mechanism

Guanshan Eqp. 0917M_L6.4

- From USGS (W-phase Moment Tensor (M_{ww})): the source rupture type belongs to strike-slip faulting, M_w = 6.53, Depth=13.5km.
- From Broadband Array in Taiwan for Seismology of Institute of Earth Sciences, Academia Sinica (AutoBATS MT) : the source rupture type also shows the strike-slip faulting, M_w = 6.5, Depth=13.5km.




(USGS)



(AutoBATS MT)

Chihshang Eqp. 0918M_L6.8

- From USGS (W-phase Moment Tensor (M_{ww})): the source rupture type belongs to oblique reverse fault, M_w = 6.93, Depth=11.5km.
- The moment tensor solution from Broadband Array in Taiwan for Seismology of Institute of Earth Sciences, Academia Sinica, including GMRT and W-Phase, have similar results.



(USGS)






GRMT
(IES、TEC)





W-Phase
(IES、TEC)

Location of the Earthquake and Fault




Spatial and Temporal Distribution of Aftershock

Phase 1: 0917M_L6.4 -> 0918 M_L6.8



Phase 2: 0918M_L6.4 -> 0919 M_L5.9



(↑Video from Chih-Wei Chang,
<https://www.youtube.com/watch?v=Ea2pmS6E2aM>)

The aftershocks of 0918M_L6.8 occurred along the longitudinal valley to the northeast, and a larger aftershock occurred on the north side on September 19.

Spatial and Temporal Distribution of Aftershock(Video)



Earthquake catalog from CWB. Video made by Chih-Wei Chang(NCREE)

NCREE Real-time Earthquake Information Display Platform

NAR Labs

Guanshan Eeq. 0917M_L6.4



地震事件：

2022-09-17 21:41 規模：6.4

地震代號：111086

發震時間：2022-09-17 21:41:19

芮氏規模：6.4

發震深度：7.3KM

發震地點：臺東縣政府北方 35.8 公里 (位於臺東縣關山鎮)

最大震度：6強

震央經緯度：121.163, 23.0777

[中央氣象局連結](#)

[中央研究院連結](#)

顯示地震動類型

地表加速度峰值

☒ 讀取地震動分布圖


事件圖檔下載

測站紀錄


- ☒ 選擇全部
- ☒ 氣象局即時站(CWBSN)
- ☒ 國震現地型震預警系統(EEWs)
- ☒ 國震即時陣列(SANTA)
- ☒ 氣象局強震網(TSMIP)

參考圖資

PGA




0.3s Sa



Integrate the real-time observation records of the CWB, the NCREE, and the ground motion parameters estimated by the advanced ground motion prediction model to display the ground motion information in real time.


1.0s Sa







Pulse-Like Ground Motion

Guanshan Eqp. 0917M_L6.4

Chihshang Station



Luye Station



NCREE Real-time Earthquake Information Display Platform

Chihshang Eqk. 0918M_L6.8



地震事件：

2022-09-18 14:44 規模：6.8 ▼

地震代號：111111

發震時間：2022-09-18 14:44:15

芮氏規模：6.8

發震深度：7KM

發震地點：臺東縣政府北方 42.7 公里 (位於臺東縣池上鄉)

最大震度：6強

震央經緯度：121.2035, 23.1375

[中央氣象局連結](#)

[中央研究院連結](#)

顯示地震動類型

地表加速度峰值 ▼

☒ 讀取地震動分布圖


事件圖檔下載

測站紀錄


- ☐ 選擇全部
- ☐ 氣象局即時站(CWBSN)
- ☐ 國震現地型震預警系統(EEW)
- ☐ 國震即時陣列(SANTA)
- ☐ 氣象局強震網(TSMIP)

參考圖資


PGA



0.3s Sa








1.0s Sa



Pulse-Like Ground Motion

Chihshang Eqp. 0918M_L6.8



South of the Gaoliao bridge about 4.6km


North of the damaged building (Yuli 7-Eleven CVS) about 1.4km.

South of the Luntian bridge about 5.5km






Observed Data and Design Spectra

Chihshang Eeq. 0918M_L6.8


Yuli Station



Chihshang Station



Fuli Station



Outline of Disaster Investigation Report

◆ Ground Motion Characteristics

◆ Damage of Buildings



◆ Damage of Bridges

◆ Geotechnical Damage

◆ Damage of Nonstructural Components and Nonbuilding Structures

◆ Information for Earthquake Early Warning, Structural Monitoring and Control

Earthquake records measured by Yuli Station




Max. horizontal acceleration : 500 gal
Spectral acceleration exceeds the MCE level in the short period range)

2022.09.20 (Tue.) Earthquake Recon. Itinerary

9/20 (Hualien)

- Convenience Store (7-11) in Yuli Township (C)
- Songpu Church (D)
- Song-Pu & Wan-Li communities (E)
- Chun-Rih elementary school (G)
- Tianxuan Church (H)



Itinerary

- 9/20 (Hualien)
 - **Convenience Store (7-11) in Yuli Township**
 - Song-Pu elementary school
 - **Songpu Church**
 - Chun-Rih elementary school
 - **Tianxuan Church**

Convenience Store (7-11) in Yuli Township

No. 135, Sec. 2, Zhongshan Rd., Yuli Township, Hualien County

- Reinforced Concrete (RC) Structure
- 1F for commercial use, 2F~4F for Residential
- 1F~3F Build in 1994 (RC Structure).
- The Roof (4F) Build in 1996 (Brick Structure)



Yuli 7-11 convenience store

Collapse along the transverse direction



GPS : (23.335760357922272, 121.31400648127511)

Telecom Company (中華電信)

No. 137, Sec. 2, Zhongshan Rd., Yuli Township, Hualien County



Chun-Rih Elementary School (春日國小)

No. 95, Tailin, Yuli Township, Hualien County



GPS : (23.4525771906309, 121.39301882730187)

NARLabs

Chun-Rih Elementary School (春日國小)

No. 95, Tailin, Yuli Township, Hualien County





GPS : (23.4525771906309, 121.39301882730187)

NARLabs



Chun-Rih Elementary School (春日國小)

No. 95, Tailin, Yuli Township, Hualien County






NAR Labs



● Partition Wall Cracking



● Exterior Wall with Windows Cracking



GPS : (23.428664316759765, 121.37356820010618)

NARLabs

Songpu Elementary School (松浦國小)

No. 212, Neighborhood 12, Yuli Township, Hualien County

● Ground Uplift




GPS : (23.431902458405215, 121.37404963477468)

NARLabs

Songpu Church (松浦天主堂)

No. 174, Songpu, Yuli Township, Hualien County

- Ground Uplift about 20 cm
- Crack Length about 7 m
- Exterior Wall Sloping



Residential in Songpu (松浦167號)

No. 167, Songpu, Yuli Township, Hualien County

- Ground Uplift, and Slope about 2° ~ 14°
- Wall Sloping (about 2°)



Residential in Songpu (松浦140號)

No. 140, Songpu, Yuli Township, Hualien County


- Ground Uplift, Cracking, and Slope about 2°
- Brick Wall Collapsed



Residential in Songpu (松浦141號)

No. 141, Songpu, Yuli Township, Hualien County

- Ground Uplift
- Plastic Hinge in Column
- Brick Wall Collapsed
- Rebar rusted



Residential in Songpu (松浦172號)

No. 172, Songpu, Yuli Township, Hualien County

- Ground Uplift
- Brick Wall Sloped about 8°



Residential in Fuyin Community (萬麗143號)

No. 143, Wanli, Yuli Township, Hualien County

- 1F for commercial use, 2F for Residential
- Exterior Cracking, Brick Wall Collapsed



Residential in Fuyin Community (萬麗145號)

No. 145, Wanli, Yuli Township, Hualien County

- Wood Structure
- Ground Uplift



Residential in Fuyin Community (萬麗148號)

No. 148, Wanli, Yuli Township, Hualien County

- The uplift of the ground raises the structure about 5 cm



Residential in Fuyin Community (萬麗112號)

No. 112, Wanli, Yuli Township, Hualien County

● Ground Uplift and Cracking

● Water Pipe Breakage



Residential in Fuyin Community (萬麗108號)

No. 108, Wanli, Yuli Township, Hualien County

- Column and Wall Collapsed (Rebar for Column is #3)



Tianxuan Church (天宣道院)

No. 107, Yuli Township, Hualien County

- Longitudinal Rebar is #8
- Transverse Rebar is #3

● The First Floor Column Runs Through The Slab(Punching Shear)



- Spacing of Stirrup is 25 cm
- Width of Column is 50 cm

Wanan Elementary School (萬安國小)

No. 36, Chihshang Township, Taitung County




Zhangbin Elementary School (長濱國小)

No. 11, Changbin, Changbin Township, Taitung County



Flexural Cracking in Beam



Outline of Disaster Investigation Report

◆ Ground Motion Characteristics

◆ Damage of Buildings

◆ Damage of Bridges

◆ Geotechnical Damage


◆ Damage of Nonstructural Components and Nonbuilding Structures

◆ Information for Earthquake Early Warning, Structural Monitoring and Control

Members of Reconnaissance Team




2022/9/19 (MON)



- A** 台東機場 Taitung Airport
- B** 寶華橋 Baohua Bridge
- C** 電光大橋 Dianguang Bridge
- D** 崙天大橋 Luntian Bridge
- E** 長富大橋 Changfu Bridge

2022/9/20 (TUE)



A	高寮大橋	Gaoliao Bridge
B	玉里大橋	Yuli Bridge
C	玉里超商(7-11)	Yuli (7-Eleven)
D	瑞穗大橋	Ruisui Bridge
E	春日國小	Chunrih Elementary School
F	天宣道院	Tianxuan Temple

Location of damaged bridges



1. Baohua Bridge(1/2)

Construct Year	1984/4 (39y)
Length	680m
Structure Type	Plate girder bridge





鹿野測站

鹿野 (LONT) 震度: 5弱

地震資訊: 2022/09/18 14:44:15
震央位置: 東經121.20度, 北緯23.14度
深度: 7.0公里, 芮氏規模: 6.8

測站資訊: 2022/09/18 14:44:00
測站位置: 東經121.13度, 北緯22.91度



1. Baohua Bridge(2/2)



large displacement at expansion joint, support serious damage



Deck displacement, guardrail and attached pipe broken

2. Dianguang Bridge

Construct Year	1988/11 (34y)
Length	720m
Structure Type	Plate girder bridge

池上測站

池上 (ECS) 震度: 6強

地震資訊
發生時間: 2022/09/18 14:44:15
震央位置: 東經121.20度, 北緯23.14度
震源: 7.0公里, 芮氏規模: 6.8


測站資訊
記錄起始時間: 2022/09/18 14:44:00
測站位置: 東經121.22度, 北緯23.10度
震央距: 4.94公里, 方位角: 341.01度

PGA (Z Max) = 429 gal


PGA (NS, EW Max) = 426 gal



Guardrail damage



Response Spectrum (ECS)



3. Luntian Bridge(1/3)

Construct Year	1982/6 (41y)
Length	450m
Structure Type	Plate girder bridge


海端測站

海端 (EHD) 震度: 5強




地震資訊: 2022/09/18 14:44:15
震央位置: 東經121.20度, 北緯23.14度
深度: 7.0公里, 芮氏規模: 6.4

PGA (Z Max) = 239 gal


PGA (NS, EW Max) = 300 gal



Response Spectrum (EHD)



3. Luntian Bridge(2/3)



Bridge falling and large residual displacement

3. Luntian Bridge(3/3)



Bridge falling and bridge column fracture

4. Changfu Bridge

Construct Year	1997/11 (25y)
Length	450m
Structure Type	Plate girder bridge


玉里測站

玉里 (EYUL) 震度: 6弱


地震資訊: 2022/09/18 14:44:15
震央位置: 東經121.20度, 北緯23.14度
深度: 7.0公里, 芮氏規模: 6.8

PGA (Z Max) = 476 gal

PGA (NS, EW Max) = 500 gal



Response Spectrum (EYUL)



Large displacement at expansion joint



5. Yuli Bridge


Construct Year	1977(North) 、 1994(South)
Length	575m
Structure Type	Girder bridge

玉里測站


玉里 (EYUL) 震度: 6弱

地震資訊
發生時間: 2022/09/18 14:44:15
震央位置: 東經121.20度, 北緯23.14度
深度: 7.0公里, 芮氏規模: 6.8

測站資訊
記錄開始時間: 2022/09/18 14:44:00
測站位置: 東經121.32度, 北緯23.35度
震中距: 26.06公里, 震中方位: 206.99度



Response Spectrum (EYUL)





Damage at expansion joint

6. Gaoliao Bridge(1/4)

Construct Year	1991 (32y)
Length	879.1m
Structure Type	PCI girder bridge



Original



Broken

6. Gaoliao Bridge(2/4)

On bridge side



Off
bridge
side




East Abutment : pavement and retaining wall collapse

6. Gaoliao Bridge(3/4)



**Upstream
direction**



Column and Base : Collapse 、 Fracture

6. Gaoliao Bridge(4/4)



Bridge falling



PCI girder



Shear key

Superstructure : Bridge falling, collapse


7. Ruisui Bridge

Construct Year	1975(North) 、 1990(South)
Length	700m
Structure Type	Girder bridge




紅葉測站

紅葉 (EHY) 震度: 5弱



Response Spectrum (EHY)



pavement, guardrail slight damage



Outline of Disaster Investigation Report

◆ Ground Motion Characteristics

◆ Damage of Buildings

◆ Damage of Bridges



◆ Geotechnical Damage

◆ Damage of Nonstructural Components and Nonbuilding Structures

◆ Information for Earthquake Early Warning, Structural Monitoring and Control

Itinerary

- 9/19 (Hualien)
 - Chun-Rih Elementary School
 - Song-Pu Elementary School
 - Gao-Liao Bridge (East side)
 - Sixty Stone Mountain
 - Gao-Liao Bridge (West side)
- 9/20 (Taitung)
 - Southern Cross-Island Highway (141K+500, 164K, 174K, 192K, 191K, 195K)
 - Fu-Li



Location coordinates of 9/19

Date	Location	Focus	Coordinates
9/19	Chun-Rih Elementary School	Building, Foundation	23.452321, 121.392933
	Song-Pu Elementary School	Building, Foundation	23.428478, 121.373582
	Structure near the Song-Pu Elementary School	Building, Foundation	23.428064, 121.373257
	Gao-Liao Bridge (East side)	Bridge, Foundation	23.384818, 121.348445
	Sixty Stone Mountain	Slop, Landslide, Geology	23.219629, 121.299467
			23.215441, 121.301890
			23.215177, 121.302079
			23.214465, 121.303679
			23.214369, 121.302778
			23.219573, 121.300230
			23.218935, 121.300123
			23.219659, 121.300083
	Dong-Li Station	Building, Foundation, Railway	23.272492, 121.304144
	Gao-Liao Bridge (West side)	Bridge, Foundation	23.385727, 121.337124

Location coordinates of 9/20

Date	Location	Focus	Coordinates
9/20	Southern Cross-Island Highway	Slop, Landslide, Geology	23.132383,121.134640
			23.177604,121.024732
			23.266750,120.952960
			23.138576,121.106105
			23.135566,121.130808
			23.135134,121.131437
			23.134602,121.131717
			23.134324,121.132225
			23.133864,121.132833
			23.133276,121.133574
			23.132732,121.134341
			23.132370,121.135324
			23.132174,121.136219
	Fu-Li	Soil Liquefaction	23.206597,121.272588

Chun-Rih Elementary School

- The building did not collapse when the M_L 6.4 earthquake occurred on 9/17.
- The M_L 6.8 earthquake on 9/18 caused the collapse of the connecting corridor, and the entire wall was tilted.
- There are many cracks in the kindergarten classrooms, toilets, and kitchens adjacent to the collapsed corridor.



Song-Pu Elementary School

- The buildings and roads opposite to the elementary school were pushed towards Song-Pu elementary school, and the pushing direction was from southeast to northwest.
- Opposite to the elementary school, the concrete floor was squeezed and raised by about 40 cm.



Gao-Liao Bridge (East side)

- Abutment damage camber, bridge deck subsidence.
- The water pipeline is damaged resulting in water service outage to the downstream residents.
- Retaining wall is without reinforcements.



Gao-Liao Bridge (East side)

- Soil loss due to the collapse of the second retaining wall on the east entrance of the bridge.
- The retaining walls were pushed out by the earthquake (mainly pushed toward north).
- The maximum subsidence of the subgrade elevation of the entry wall is about 1 meter.



Gao-Liao Bridge (East side)

- Compared with the south and north retaining walls on the outside of the culvert under the abutment, there is an inward shrinkage.
- The difference between the south retaining wall and the culvert is about 15 cm. The difference between the north retaining wall and the culvert is about 45 cm.



Gao-Liao Bridge (East side)

- Three piers from the east abutment were completely destroyed.
 - The first pier is located at the border of the bridge deck and is covered with steel plates. The pier is completely collapsed, but there is no obvious structural damage.
 - The second pier was located in the middle of the deck and was damaged by shear force.
 - The third pier was not clad with steel plates, and the damage was similar to the first pier.



Gao-Liao Bridge (West side)

- The spacing between the main rebar is about 13-20cm.
- Stirrup spacing is about 12-15cm.
- Caisson foundation under the pier.



Sixty Stone Mountain

- The mountain road is damaged by many rock falls and there are signs of continuity of such.
- It is estimated that the largest area may be 100 meters long and 30 meters wide, and the largest diameter of the rock block may be up to 5 meters.



Dong-Li Train Station

- The roof of the train station platform fell and the train derailed.
- The railway is seriously deformed.
- The base unit carrying the ballast is separated, resulting in the loss of ballast.



Southern Cross-Island Highway



Landslide



Southern Cross-Island Highway

- The rockfall materials can be roughly categorized into rocks (metamorphic sandstone, schist) and river grade gravel.



141K+500



195K

Fu-Li

- A suspected liquefaction phenomenon found in Fu-Li.
- No building damage due to soil liquefaction was observed.



Outline of Disaster Investigation Report

◆ Ground Motion Characteristics

◆ Damage of Buildings

◆ Damage of Bridges

◆ Geotechnical Damage

◆ Damage of Nonstructural Components and Nonbuilding Structures

◆ Information for Earthquake Early Warning, Structural Monitoring and Control

Earthquake Reconnaissance Locations

Nonstructural Components and Equipment

Hospital



Kuanshan Tzu Chi Hospital
(關山慈濟醫院)



Taitung Hospital Chenggong Branch
(台東醫院成功分院)



Taitung Christian Hospital
(台東基督教醫院)

Shopping mall



Dream mall (高雄夢時代)





IKEA Hsin Chuang Store
(新莊IKEA)

Hou-Hu Columbarium Pagoda (鹿野后湖納骨塔)



Taoyuan City Bade Civil Sports Center (八德運動中心)




Nonbuilding Structures

Rice mill



Xin-Qian-Kun rice mill
(關山新乾坤碾米廠)



Guan-Shan township Farmers' association rice mill
(關山鎮農會碾米加工廠)

Gravel factory

Lei-Xin ready mixed plant (玉里磊信水泥廠)



Hao-Ye ready mixed plant (池上灝業採石場)



Zhi-Sheng ready mixed plant (關山志昇預拌廠)




Reconnaissance Route (East Taiwan)

A	Zhi-Sheng ready mixed plant, Guan-Shan township, Taitung	關山/志昇預拌混凝土廠
B	Xin-Qian-Kun rice mill, Guan-Shan township, Taitung	關山/新乾坤碾米廠
C	Farmers' association rice mill, Guan-Shan township, Taitung	關山/農會碾米加工廠
D	Hao-Ye ready mixed plant, ChihShang township, Taitung	池上/灝業採石場
E	Kuanshan Tzu Chi Hospital, Guan-Shan township, Taitung	關山/慈濟醫院

19 Sep.

Guan-Shan Earthquake




20 Sep.

ChihShang Earthquake

Guan-Shan Earthquake

A	Hou-Hu Columbarium Pagoda, Lu-Ye township, Taitung	鹿野/后湖納骨塔
B	Lei-Xin ready mixed plant, Yu-Li township, Hua-Lien	玉里/磊信混凝土預拌廠
C	Nian-Chang rice mill , Yu-Li township, Hua-Lien	玉里/年昌碾米廠
D	Xie-Tian Temple, Yu-Li township, Hua-Lien	玉里/協天宮
E	Taitung Christian Hospital, Taitung	台東/基督教醫院




Taitung Christian Hospital (台東基督教醫院), Taitung County

- **RO water system was damaged in Guan-Shan Earthquake (17 Sep.)**



RO water filters are girdled and fixed by metal rings
(No damage to filters and connected pipes)

Comparing to the freestanding RO water filters in Taitung Hospital Chenggong Branch, the connection pipe was damaged during 0323, 2022 Hualien Earthquake.





Connection pipe damage
(It is speculated that the filters are inconsistent with movement of adjacent motors)

RO water filters are girdled and fixed by metal rings
(Connection pipe damage)




Taitung Christian Hospital (台東基督教醫院), Taitung County

StationCode: S00054
2022/09/17-21:40:54.690




Freestanding RO water tank
(without any anchorage)

Originally, the two ends marked with green circles were connected to each other with a pipe. After earthquake, the pipe was broken and a transparent hose connection was temporarily used to keep its functionality.




Kaohsiung/Dream Mall


StationCode: KAU106
2022/09/17-13:40:49.000




Response Spectrum (KAU106)




Relative displacement of expansion joint occurred on the 5th floor



Relative displacement of expansion joint occurred on the 8th floor



Relative displacement of expansion joint occurred on the 9th floor



Kaohsiung/Dream Mall

Architectural Component :
interior veneer and ornamentations

Damage to the interior veneer and ornamentations was investigated due to the relative displacement of expansion joint on 5th, 8th and 9th floor.



Kaohsiung/Dream Mall


Architectural Component : Suspended Ceilings

- The boundary, an unbraced gypsum board, on the side of the ceiling is adjacent to the expansion joint, which was damaged during the earthquake.
- Damage to the unbraced gypsum panel led to fallen ceiling panels and deformed ceiling runners.
- Rods are used as the suspension system. The suspension length of the ceiling is approximately 2.5 m to 3.0 m.





Hou-Hu (后湖) Columbarium Pagoda

Lu-Ye township, Taitung County




StationCode: TTN045
2022/09/17-13:40:49.000



Ossuary cabinets in 1st to 3rd floor are collapsed



Water tank of outdoor public toilet fell from the roof





Hou-Hu (后湖) Columbarium Pagoda

Lu-Ye township, Taitung County

Nonstructural Component : Contents

- **On the first floor**, one of the ossuary cabinets, not attached to any other structural components, was collapsed westward.
- **No anchorage observed** at the bottom of the cabinet.
- The steel wires connecting to the top of the cabinet and the above slab failed during Guan-Shan Earthquake.



Hou-Hu (后湖) Columbarium Pagoda

Lu-Ye township, Taitung County



- **On the second floor**, one of the ossuary cabinets, which was not attached to any other structural components, **was collapsed westward**.
- The **bottom steel supporting frame** secured to the floor by **thin L-shaped sheet metals and plastic nylon anchors** failed.
- The **steel wires** connecting the above slab and the top of the cabinet failed.
- **Doors opened and the urns dropped**.







Hou-Hu (后湖) Columbarium Pagoda

Lu-Ye township, Taitung County

- The cabinets **on the third floor** were built recently.
- One of the ossuary cabinets, which was not attached to any other structure components, **was collapsed eastward**.
- **Failure of the hook of a turnbuckle** was observed. This may lead to the failure of the cable system above the cabinet.
- **Aluminum skeletons with cross section behind the cabinet ruptured** from the aluminum bottom plate, which was supposed to be fixed on the floor.




Taoyuan/Bade (八德) Civil Sports Center





The ceiling was completely collapsed during the ChihShang Earthquake

Taoyuan/Bade (八德) Civil Sports Center



Xin-Qian-Kun (新乾坤) rice mill

Guan-Shan township, Taitung County




The failure of the supporting frame underneath the tanks led to the grain tanks collapsed toward southwest in 9/17 event.



South side of the tanks

Xin-Qian-Kun (新乾坤) rice mill Guan-Shan township, Taitung County



- The inner beams were secured on a tiny steel plate, which were simply welded to the outer beam, with 4 bolts.
- The welding strength was not sufficient, and the beams fell during the earthquake.




- Some of the bolts used to secure the columns and beams were sheared.
- The lower beams were just placed on the floor without any anchorage.





Buckled H-beam

Zhi-Sheng (志昇) ready mixed plant Guan-Shan township, Taitung County

Before earthquake (from Google map)





- Storage tanks of gravel and cement collapsed.



Zhi-Sheng (志昇) ready mixed plant Guan-Shan township, Taitung County

Sand and gravel tank


- The tank was supported by a steel frame, and there were 12 steel posts underneath it.
- The bolts pulled off due to the tensile force.
- The posts ruptured at the welding spots.



Zhi-Sheng (志昇) ready mixed plant Guan-Shan township, Taitung County

Cement tank

- One of the cement tanks collapsed in the Guan-Shan Earthquake. Shear failure of bolts of another tank occurred as well.
- The tank was emergency repaired by welding and survived in ChihShang Earthquake.




Outline of Disaster Investigation Report


- ◆ Ground Motion Characteristics
- ◆ Damage of Buildings
- ◆ Damage of Bridges
- ◆ Geotechnical Damage
- ◆ Damage of Nonstructural Components and Nonbuilding Structures
- ◆ Information for Earthquake Early Warning, Structural Monitoring and Control

Intensity Maps of Two Earthquakes



2022 年第 086 號 有感地震





2022 年第 111 號 有感地震



NCREE EEWs Trigger and Alarm




NCREE EEWS Predicted and Measured PGA




2022/09/17 21:41 M_L 6.4

Predicted Intensities (CWB-Old)




Measured Intensities (CWB-Old)




2022/09/18 14:44 M_L 6.8

Predicted Intensities (CWB-Old)




Measured Intensities (CWB-Old)



NCREE EEWS Advanced Warning Time


No. 086

Time (sec)





No. 111

Time (sec)



NCREE Building Seismic Array TSMOD

Taiwan Structural Monitoring Data Hub <http://bas.ncree.org/>



Hualien Tzu Chi Hospital



Photo is from internet


Completed in 2005.02

Hualien Tzu Chi Hospital


Base Isolation System

B2~1F SRC Structure · 1F ~ 11F RC Structure

Use Seismic Design Specifications and Commentary of Buildings in 1997



Strong Motion Instrument



CH1~CH26 : Accelerometer
CH27~CH30: Displacement meter




2022/09/17 21:41 Accelerations of CH1~CH3

No. 086

2022/09/17 21:41



M_L 6.4



2022/09/17 21:41 Acceleration of Others

No. 086

2022/09/17 21:41
M_L 6.4




2022/09/18 14:44 Accelerations of CH1~CH3

No. 111

2022/09/18 14:44

M_L 6.8





2022/09/18 14:44 Acceleration of Others

No. 111

2022/09/18 14:44

M_L 6.8



Maximum Acceleration of Each Floor

No. 086
20220917

unit: gal

Floor	Longitudinal	Transversal	Virtual
11F	23	26	6
5F	15	15	
4F	15	15	
B1F	14	15	5
B2F	11	8	5
11F / B2F	213.71%	339.04%	116.15%
5F / B2F	144.71%	194.64%	
4F / B2F	137.90%	192.06%	
B1F /B2F	132.89%	190.43%	97.90%

No. 111
20220918

unit: gal

Floor	Longitudinal	Transversal	Virtual
11F	47	62	22
5F	42	40	
4F	37	42	
B1F	36	49	15
B2F	34	33	15
11F / B2F	138.01%	190.22%	152.35%
5F / B2F	123.51%	123.69%	
4F / B2F	110.57%	127.36%	
B1F /B2F	107.68%	151.16%	101.76%


Horizontal acceleration ratios are significantly lower for 09/18 earthquake.

Subspace Identification Results

No. 086

2022/09/17 M_L 6.4

慈濟醫院急診大樓, SI Analysis




No significant variation of fundamental period
Base isolation remained elastic stage

No. 111

2022/09/18 M_L 6.8

慈濟醫院急診大樓, SI Analysis



Significant variation of fundamental period
Damping ratios increase
Base isolation went through inelastic stage

Future Work

- ✚ NCREE will continue to collaborate with local and central governments, the engineering industry and the academic community to investigate the severely impacted area and to study and propose measures for improvement, aiming to reduce losses induced by future earthquakes.

The End