



**NAR Labs** 國家實驗研究院

**國家地震工程研究中心**

National Center for Research on Earthquake Engineering

# Summary Report of Hualien Earthquake in Taiwan on April 3, 2024 (2<sup>nd</sup> edition, V2.0)

**Chung-Che Chou, Chiun-Lin Wu, Juin-Fu Chai, George C. Yao**

**NCREE, Taiwan**

**May 25, 2024**

[www.ncree.narl.org.tw](http://www.ncree.narl.org.tw)

版權所有© 2024 國家地震工程研究中心(NCREE)

# Members of the Emergency Response Team

---

## Chairperson: Chung-Che Chou

Emergency Response Operation Manager (Deputy Chairperson): Chiun-Lin Wu

Deputy Emergency Response Operation Manager: Juin-Fu Chai

Executive Secretary: Chi-Hao Lin

Disaster Summary : Bo-Han Lee

## Disaster Information Collection

Chun-Chung Chen, Chih-Shian Chen, Hsiao-Hui Hung, Jyun-Yan Huang, Yu-Wen Chang,  
Shih-Liang Chen, Che-Min Lin, Chin-Hsun Yeh, Shu-Hsien Chao, Zheng-Kuan Lee,  
Chia-Chuan Hsu, Jui-Liang Lin, Tsung-Chih Chiou, Min-Lang Lin, Yuan-Tao Weng,  
Te-Kuang Chow, Hsuan-Chih Yang, Che-Yu Chang, Shang-Yi Hsu, Fan-Ru Lin,  
Tzu-Chieh Chien, Zhen-Yu Lin, Wei-Hung Hsu, Wei-Chung Chen, Bai-Yi Huang,  
Ching-Hsien Huang, Chung-Han Yu, Chieh-Min Ho, Lee-Hui Huang

# Outline

---

◆ Seismic Source and Ground Motion Characteristics

◆ Early Seismic Loss Estimation

◆ NCREE EEWS Performance

◆ Bridge Damage

◆ Building Damage

◆ Geotechnical Damage

◆ Non-Structural Component (NSC) Damage

# Outline

---

◆ Seismic Source and Ground Motion Characteristics

◆ Early Seismic Loss Estimation

◆ NCREE EEWS Performance

◆ Bridge Damage

◆ Building Damage


◆ Geotechnical Damage

◆ Non-Structural Component (NSC) Damage



# The 3<sup>rd</sup> Apr. 2024, Hualien, Taiwan earthquake


- A local magnitude  $M_L$  7.2 earthquake occurred at 7:58:09 on 3<sup>rd</sup> Apr. 2024 local time (UTC+8). The epicenter is located offshore Hualien (25 km from the government building of Hualien County at SSE direction). The intensity was reported as 6+ in 和平, 6- in Hualien City and 太魯閣, and 5- in Taipei and New Taipei city.
- The epicenter is located at N  $23.77^\circ$ , E  $121.67^\circ$ , and the epicenter depth is 15.5km.



From Central Weather Administration

# Focal Mechanism


- The USGS's W-phase and Centroid Moment Tensor announcement indicates reverse faulting, in which the resolved moment magnitude ( $M_w$ ) is 7.37 and the focal depth is 23.5 km.
- The Global Real-Time Moment Tensor Monitoring System by IES resolved a similar focal mechanism with the USGS. The resulting  $M_w$  is 7.66, and the focal depth is 35.5 km.
- Incorporated Research Institutions for Seismology (IRIS) IES resolved a similar focal mechanism.



(USGS)





(GRMT, IES)



(IRIS)

# Aftershock Activities



- The Central Weather Administration (CWA) announced 1416 aftershocks until 11:02 on 9th May, including four events with magnitudes greater than  $M_L$  6.0. The highest intensity of this event is 5+.







# PGA and PGV Map by CWA

0403 M<sub>L</sub> 7.2, Depth 15.5km



# Spectral Acceleration Maps

0403  $M_L$  7.2, Depth 15.5km



# Time Histories


**NAR Labs**

**0403 M<sub>L</sub> 7.2, Depth 15.5km**

From Central Weather Administration


**Heping (EHP), Int.= 6-**

Stalon=121.75, Stalat=24.31, Dist.= 60.42km, BAZ=188.17




**Hualien City (HWA), Int.= 6-**

Stalon=121.61, Stalat=23.98, Dist.= 23.41, BAZ=167.05




**Taroko (ETL), Int.= 6-**

Stalon=121.62, Stalat=24.16, Dist.= 43.37, BAZ=174.33



**Aohua (EAH), Int.= 5+**

Stalon=121.74, Stalat=24.33, Dist.= 62.51, BAZ=186.94









# Observed Data and Design Spectra

11

**NAR Labs**

0403 M<sub>L</sub> 7.2, Depth 15.5km




DBE and MCE for Horizontal


# Pulse-Like Velocity Time Histories

- Three stations observed the pulse-like velocity (velocity pulse) from the Taiwan Rapid Earthquake Information Release System (RTD) till 15:30 on 3rd Apr. The extracted pulses are derived from Shahi and Baker's 2014 method. The corresponding pulse periods are 3.4 to 3.7 seconds.
- The PGV observed near the source at 和平、Hualien city are 65.7cm/s and 56.3cm/s, which are larger than the three stations but did not extract a velocity pulse.


0403M<sub>L</sub> 7.2 earthquake – ILA  
PGV= 40.8 cm/s; Tp= 3.416s  
Direction: N21.7° W



0403M<sub>L</sub> 7.2 earthquake – NJN  
PGV= 29.4 cm/s; Tp= 3.668s  
Direction: S40.9° E



0403M<sub>L</sub> 7.2 earthquake – FUS  
PGV= 31.6 cm/s; Tp= 3.626s  
Direction: N57.5° W





# Pulse-Like Velocity Time Histories

- There are 11 additional pulse-like velocity time history observed by the TSMIP stations, listed as follows:

Station codes	Longitude	Latitude	Pulse Period(s)	PGV(cm/s)
ILA	121.76	24.76	3.4	40.8
FUS	121.24	24.25	3.6	31.6
NJN	120.87	24.68	3.7	29.4
ILA004	121.7907	24.7435	2.9	55.4
ILA006	121.8327	24.6397	3.1	50.9
ILA026	121.7728	24.6733	4.0	49.2
ILA037	121.7228	24.7435	2.5	42.5
ILA042	121.7987	24.6875	2.9	59.3
ILA046	121.7423	24.6650	3.4	27.2
ILA049	121.7563	24.7638	3.4	40.9
ILA059	121.8297	24.6655	3.4	55.5
ILA068	121.8573	24.5972	1.5	36.6

# Pulse-Like Velocity Time Histories

---

- There are 11 additional pulse-like velocity time history observed by the TSMIP stations, listed as follows:

Station codes	Longitude	Latitude	Pulse Period(s)	PGV(cm/s)
TCU033	120.8703	24.6835	3.9	33.6
TCU035	120.7970	24.6142	3.7	25.4

# CWA Earthquake Report for the Largest aftershock


## ■ Earthquake No.: 113021

Origin time (Taiwan Standard Time: GMT+08:00): 4/ 3/2024 8:11:26.2

Location: 24.10N 121.66E, i.e. 12.7 km NNE of Hualien County



Depth : 5.5 km

Magnitude( $M_L$ ): 6.5



From Central Weather Administration

# Spectral Acceleration Maps

**0403  $M_L$  6.5, Depth 5.5km**

# Time Histories


**NAR Labs**

**0403 M<sub>L</sub> 6.5, Depth 5.5km**

From Central Weather Administration



**Hualien City (HWA), Int.= 5-**

Stalon=121.61, Stalat=23.98, Dist= 14.64, BAZ= 18.50




**Tongmen (ETM), Int.= 5-**


Stalon=121.49, Stalat=23.97, Dist= 22.54, BAZ= 48.66



**Response Spectrum (HWA)**



**Response Spectrum (ETM)**



DBE and MCE for Horizontal

# Outline

---

- ◆ Seismic Source and Ground Motion Characteristics
- ◆ Early Seismic Loss Estimation
- ◆ NCREE EEWS Performance
- ◆ Bridge Damage
- ◆ Building Damage
- ◆ Geotechnical Damage
- ◆ Non-Structural Component (NSC) Damage



# Seismic Source Parameters Assumed


Depth : 15.5~35.5km

● Magnitude :  $M_L 7.2$  、  $M_W 7.37 \sim 7.66$

● Direction & Dip : USGS Focal mechanisms


## Scenario 1

- Sloping northwestward
- Subduction interface GMPE



## Scenario 2


- Sloping southeastward
- Reverse fault GMPE



# Estimation of building damage


## Scenario 1

● Estimated result : about 78 buildings at least severe damaged.



## Scenario 2

● Estimated result : about 650 buildings at least severe damaged.




The exact number of damaged buildings awaits further investigation and statistics !



# Estimation of casualties


## Scenario 1

● Estimated result : about 7 people severely injured or killed



## Scenario 2

● Estimated result : about 104 people severely injured or killed



The exact number of casualties awaits further investigation and statistics !

SubTotal	Min...	Max...
<input checked="" type="checkbox"/>	0	0.1
<input checked="" type="checkbox"/>	0.1	0.2
<input checked="" type="checkbox"/>	0.2	0.5
<input checked="" type="checkbox"/>	0.5	1
<input checked="" type="checkbox"/>	1	2
<input checked="" type="checkbox"/>	2	5
<input checked="" type="checkbox"/>	5	10
<input checked="" type="checkbox"/>	10	20
<input checked="" type="checkbox"/>	20	50
<input checked="" type="checkbox"/>	50	70

# Outline

---


- ◆ Seismic Source and Ground Motion Characteristics
- ◆ Early Seismic Loss Estimation
- ◆ Isolated Building Damage
- ◆ Building Damage
- ◆ Geotechnical Damage
- ◆ Non-Structural Component (NSC) Damage

# Hualien Tzu Chi Medical Center


**NAR**Labs



- Without any structural damage and damage in isolation system.
- Minor nonstructural damages due to movement of isolation system.









# Surrounding Areas of He Xin Building





The maximum pushing displacement (isolation displacement) in longitudinal dir. could be roughly measured as 300mm

**Damages of stone slabs due to insufficient isolation moving space**



# Surrounding Areas of He Xin Building



**400mm in  
transverse direction**

**Damages of garden  
stone pillars due to  
insufficient isolation  
moving space**





# Surrounding Areas of He Xin Building

Insufficient isolation moving space





# Surrounding Areas of He Xin Building




**Insufficient isolation moving space**

**Measured residual displacement :**  
**Longitudinal < 30mm;**  
**Transverse < 50mm**



# Inspection of Isolation System

**NAR Labs**



**Residual displacement in longitudinal dir.: 15mm**



**Residual displacement in transverse dir.: 1mm**



**Residual displacement in longitudinal dir.: 52mm**




**Residual displacement in transverse dir.: 51mm**




**Measurement from recording panel.  
(The residual displacements correspond to original location)**

# Defects in Isolation Layer






# Instrumentation of He Xin Building **NAR Labs**



CH1~CH26 : Accelerometer


CH27~CH30: Displacement transducer

# Instrumentation of He Xin Building **NAR Labs**




# Input Excitations

## Acceleration history records at the center of base floor





# Acceleration Records of Each Floor



# Peak Acceleration Values of Each Floor

---

(unit: gal)

Floor	longitudinal	transverse
11F	152	290
5F	148	202
4F	135	198
B1F	152	200
B2F	194	209
11F / B2F	78%	139%
5F / B2F	76%	97%
4F / B2F	70%	95%
B1F / B2F	78%	96%

# Input Excitation Spectra

Design values from static analysis:

Effective period = 2.76sec

Equivalent damping ratio = 28%

Design displacement = 238.48mm



Total design displacement = 292.51mm

Design values from spectrum analysis :

Design displacement = 350mm

Actual design displacement = 600mm


Actual isolation gap = 700mm





# Comparison of Input Excitation Spectra

Normalized  
to EPA=1g



# Outline

---

- ◆ Seismic Source and Ground Motion Characteristics
- ◆ Early Seismic Loss Estimation
- ◆ Isolated Building Damage
- ◆ Building Damage
- ◆ Geotechnical Damage
- ◆ Non-Structural Component (NSC) Damage

Damaged bldg.

# 5-story Residential bldg. Hualien City

**NAR**Labs



民視新聞



## Soft/weak story failure



Damaged bldg.

# 5-story Residential bldg. **NAR Labs**

## Hualien City

- RC Column failure
- Bldg. inclined





**Damaged bldg.**

# 4-story Residential bldg. **NAR Labs**

## Hualien City

## Column protective layer peeling off






Damaged bldg.

# 4-story Residential bldg. Hualien City

**NAR**Labs

RC Beam-Column Connection Failure

Partition walls damaged



Damaged bldg.

NAR Labs

# School bldg. in Hualien City

windowsill shear failure






Damaged bldg.

# 6-story Residential bldg. **NAR Labs**

## Hualien City

Walls shear failure

Wall protective layer peeling off





Damaged bldg.

# 4-story Residential bldg. **NAR Labs**

## Hualien City

### The bottom of RC column crack




Damaged bldg.

# 10-story Residential bldg.

Hualien City, Hualien County

NAR Labs

- Soft/weak story failure






Damaged bldg.

# 6-story Residential bldg. **NAR Labs**

## Hualien City

RC columns at 1<sup>st</sup>-story crack  
windowsill shear failure





Damaged bldg.

# 6-story Residential bldg. **NAR Labs** Hualien City

## Severe Damage to the Ground Floor





Damaged bldg.

# Residential bldg.

**NAR**Labs

Renli 5<sup>th</sup> St., Ji'an Township, Hualien County

## RC Wall failure






**Damaged bldg.**

# Residential bldg. Hualien City

**NAR Labs**

- **RC Columns flexural failure**
- **Walls damaged severely**

距震央23.97km





Damaged bldg.

# 6-story Hotel bldg. Hualien City

**NAR**Labs

- RC Columns and walls damaged severely



Damaged bldg.

# 12-story Residential bldg. **NAR Labs**

## Hualien City

---

- RC Walls and Partition walls shear failure
- RC Columns shear failure





Damaged bldg.

# Residential bldg.

## Hualien County

**NAR**Labs

## RC Walls Shear failure






Damaged bldg.

# 14-story Residential bldg. **NAR Labs**

## Hualien City

RC Columns shear failure  
Tiles falling



Damaged bldg.


# Hotel bldg. Hualien City

**NAR**Labs

## RC Column concrete bursts, steel bars buckle



<https://www.cna.com.tw/>






Damaged bldg.

# Hotel bldg. Hualien City

**NAR**Labs

## RC Columns damaged severely






Damaged bldg.

# Hotel bldg. Hualien City

**NAR**Labs

## RC Walls shear failure



Damaged bldg.

# Commercial bldg. Hualien City

**NAR**Labs

## Non-structural walls damaged





Retrofitted bldg.

# 6-story Residential bldg. **NAR Labs**

## Hualien City

- Retrofitted with RC shear walls
- Minor cracks in stucco






Retrofitted bldg.

# Residential bldg. Hualien City

**NAR**Labs

Retrofitted with RC shear walls and wing walls



Retrofitted bldg.

**NAR**Labs

# Seismic weak-story retrofitted bldg.

## Hualien County

距震央25.83km




## Retrofitted with RC Walls

Retrofitted bldg.

NAR Labs

# Office Building Retrofitted with SBRB in Hualien City




壹層結構平面圖  
A1:1/100 A3:1/200  
比例: 1:120m 1:50cm 1:20cm 1:10cm  
2.001 2.001 2.001 2.001

↙ : SBRB Location





# Hotel Building Retrofitted with BRB in Hualien City



距震央23.53km



# School Buildings Retrofitted with RC Columns Jacketing and RC Shear Walls in Hualien City





# Elementary School Buildings Retrofitted with RC Shear Walls in Hualien City




距震央24.02km





# Retrofitted Building A00600 in Taipei City





Accelerometers were installed on the ground-floor base, the second-floor slab, and the roof slab for structural monitoring


- Seismic Intensity: 5-Weak
- Structural Damage Severity: Light
- Maximum Acceleration on 1st-floor slab: 86.2 gal
- Maximum Acceleration on 2nd-floor slab: 90.0 gal
- Maximum Acceleration on roof slab: 266 gal
- Displacement Ratio (1st floor): 0.295% (Safety threshold: 0.250%)
- Displacement Ratio (2nd floor and above): 0.146% (Safety threshold: 0.250%)

# Retrofitted Building A00600 in Taipei City

## Floor displacement time history



# Retrofitted Building A01900 in Taitong City




地震儀安裝立面圖

- Seismic Intensity: 4
- Structural Damage Severity: Light
- Maximum Acceleration on 1st-floor slab: 105 gal
- Maximum Acceleration on 2nd-floor slab: 175 gal
- Maximum Acceleration on roof slab: 319 gal
- Displacement Ratio (1st floor): 0.035% (Safety threshold: 0.02%)
- Displacement Ratio (2nd floor and above): 0.146% (Safety threshold: 0.250%)



# Retrofitted Building A0900 in Taitong City

## Floor displacement time history



# Outline

---

- ◆ Seismic Source and Ground Motion Characteristics
- ◆ Early Seismic Loss Estimation
- ◆ Isolated Building Damage
- ◆ Building Damage
- ◆ Geotechnical Damage
- ◆ Non-Structural Component (NSC) Damage

## Hualien port (1/2)


- Distance=23 km to the epicenter.
- The earthquake caused subsidence and soil liquefaction behind pier 23-25.

Location	#25
PGA(gal)	410.5
PGV(cm/s)	58.7
Sa0.3s (gal)	776.9
Sa1s (gal)	596.6

↑ \* Interpolation values.



GOOGLE MAP



<https://seaport.ncree.org/smap/>



## Hualien port (2/2)

- The backfill subsidence was most severe at pier 25. The gravel sand backfill areas behind the dock lines also showed sand boils and cracks.



Sand boils



The reinforced concrete pavement has sunk and tilted.



Pier No,	Max. Subsidence
#25	70cm
#23~#24	50cm
#19~#22*	50cm
#17~#18*	12cm

\* provided by the Hualien Port Authority.

# Meilun River

- Signs of liquefaction were observed on the left bank sandbar of the Meilun River
- Similar liquefaction phenomena were observed at the same location during the previous earthquake.



Suspected sand boils possibly caused by soil liquefaction. 73



# NSCs Reconnaissance Team

Organization	Members
National Center for Research on Earthquake Engineering	Juin-Fu Chai, George C. Yao, Jui-Liang Lin, Fan-Ru Lin, Wei-Hung Hsu, Wei-Chung Chen, Bai-Yi Huang, Min-Chi Ko, Wen-Hsuan Huang, Kun-Ru Liu
National Cheng Kung University	Yu-Lin Chung, Ya-Yu Hsiao
National Kaohsiung University of Science and Technology	Keng-Chang Kuo
National Research Institute for Earth Science and Disaster Prevention	Jun Fujiwara, Ryota Nishi
Nagoya University	Takuya Nagae, Kazuki Takaya
Tokyo University	Tatsuya Asai



# Reconnaissance buildings

\* Unit: gal. retrieved from <https://smap.ncree.org/>, 15<sup>th</sup> May

Building	City	Cl.	Constr.	Story	Basement	PGA *	S <sub>a, 0.3s</sub> *	S <sub>a, 1.0s</sub> *
Hospital bldg. A1	Hualien City	Hospital	RC	5	1	418	786	669
Hospital bldg. A2			RC	7	1	418	786	669
Hospital bldg. A3			RC	7	0	418	786	669
Hospital bldg. B1			SC	10	1	395	606	673
Hospital bldg. B2			SRC	10	1	395	606	673
Hospital bldg. C1	Shoufeng township, Hualien County	School	RC	4	1	366	714	580
University library DL			SRC	6	1	321	542	592
University bldg. D1			RC	4	0	321	542	592
University bldg. D2			RC	4	0	315	520	556
University bldg. D3	Taipei City		SC	4	0	338	581	572
University library E			RC	8	1	112	203	137
Winery warehouse F	Hualien City	Factory	RC	1	0	347	613	467

# Reconnaissance NSCs

Category	NSCs	Located buildings
Architectural components	T-bar ceilings	Hospital building A2 and C1; University building D2, D3; University library DL
	Nonstructural walls	Hospital building A2 and B1; University building D2
	Elements connected to structures	Hospital building C1
Equipment	Cooling tower	Hospital building A3 and B1
	Elevator	Hospital building C1
	Water tanks	Hospital building A1, A3 and B2
	Air conditioning	Hospital building A2, B1 and C1
	Pipelines	Hospital building A2 ,A3, B1, B2 and C1; University building D3; University library DL
Contents	Stacked cargo	Warehouse F
	Bookshelves	University library DL
	Furniture and experiment equipment	Hospital building B1

## Hospital building A2



Photo credit: General Affairs Office of Hospital A

Damaged ceiling at elevator hall on the first floor ↑




Deformed ceiling grid above the nursing station on the sixth floor ↑



Status quo (repaired)




No suspension wires adjacent to the fire expansion cutout







# University library DL

Fallen ceiling at the edge (3F)





Fallen ceiling at the edge (4F)





Damage at discontinuous area of the ceiling (6F)

Collapsed Large-area ceiling (5F)




Collapsed Large-area ceiling (6F)







# University building D2



Fallen ceilings, light fixtures, air ducts and ceiling fans (3F)



Fallen ceilings, light fixtures, and air ducts (4F)




Fallen ceiling fans



## University building D3

The pitched roof caused varying suspending lengths→

Damage concentrated on the T-bar ceilings ↓





## Hospital building A2

Shear cracks of the masonry walls of the wards on the fifth and sixth floors were observed.

Damaged masonry walls (5F)




Cracked tiles on the opposite side of the wall

## Hospital building B1



Tilted lightweight aggregate concrete (LWAC) walls  
(6F & 8F)



The boundary of the  
damaged wall (8F)



## University building D2



Collapsed windproof walls, composed of LWAC (rooftop)



Failed anchorage of the collapsed wall




Partially-damaged windproof wall



# Hospital building C1



A beam connected to decorative gables collapsed on the penthouse



Another intact penthouse




# Hospital building A3 and B1





# Hospital building C1




Unfixed Rubber pads

The hoist machine of Elevator D had permanent displacement and shifted cable



Shifted cable



Falling of counterweight blocks of Elevator C



Falling of counterweight blocks of Elevator A



# Hospital building A1 and A3



Collapsed tanks at rooftop of Bldg. A1




Damaged piping joints connected to the hot water tank in Bldg. A3 (repaired)





## Hospital building B2

FRP tanks in the basement



- In the basement, there are four FRP tanks, each with slight variations in form. The FRP panels are joined with angle steel. The innermost tank suffered damage.
- Among the four tanks, only the angle steel of the damaged one was not well-connected. The connection joints were damaged during the earthquake, resulting in tearing and damage to the FRP tank wall. ↗



Tearing and damage to the FRP tank wall


Damage to the connection joints





## Hospital building A2

Excessive displacement of the pre-cooling air conditioning unit led to the rupture of the chilled water pipe connected to it (5F)




Excessive displacement of the air conditioning unit led to complete rupture of the adjacent fire sprinkler head due to impact (6F)







## Hospital building B1



Broken pipeline connected to air-conditioning unit



Suspended spring isolator



Anchorage failure



Separated ventilating machine and ductworks

## Hospital building C1



Status quo (repaired)




Excessive displacement of the small fan-coil unit resulted not only in the rupture of the connected water pipes but also in the shear failure of the suspension rods





# Hospital building C1

The repaired connecting pipeline of RO water storage tank



fracture of PVC pipe



Freestanding water storage tank

# University library DL and building D3

Damaged ductworks (6F of Bldg. DL)



Dislocation of the bath modules led to pipeline damage (4F of Bldg. D3)





## Winery warehouse F

Several confined wine jars dropped



Unconfined stacked wine jars collapsed



Collapsed stacked boxes



Collapsed stacked boxes





# University Library DL

Collapsed CD shelves (2F)




Deformed supporting frame


Deformed transverse ties (2F)



Collapsed Bookshelves (5F)



Dropped end panel (3F~6F)




Dropped books (1F~6F)



# Laboratories on 10<sup>th</sup> floor of Hospital building B1




Partition wall damaged due to the tilted furniture



Overtured cylinder rack



Partition wall damaged due to the displaced refrigerator




Ceiling damaged due to the displaced table



Partition wall hit by adjacent cabinets



Experiment equipment was fallen and fired, and triggered the fire protection system.



Burnt marks on the floor



**Thank you for your attention**